


$$V = \frac{6000}{\sqrt{3}} \times \frac{400}{6300} \times \frac{230}{400} = \frac{219}{\sqrt{3}} = 124,6 \text{ V}$$



$$X_{a1} + X_{a2} = X_T = 12,9 \text{ m}\Omega$$

$$\bar{Z} = \frac{230/\sqrt{3}}{I_c} \angle \arccos 0,92 = 0,16 \angle 23,1^\circ = 0,15 + j 0,062$$

$$I_c = \frac{300 \times 10^3}{\sqrt{3} \times 230 \times 0,92} = 819,5 \text{ A}$$

$$X_{a1} = 905 \times \frac{230^2}{400 \times 10^3}$$

$$X_{a1} = 6,6 \text{ m}\Omega$$

$$X_{a2} = 906 \times \frac{230^2}{500 \times 10^3}$$

$$X_{a2} = 6,3 \text{ m}\Omega$$

2)

$$I = \frac{124,6}{j 12,9 \times 10^{-3} + 0,16 \angle 23,1^\circ} = \frac{124,6}{0,15 + j 0,076} = \frac{124,6}{0,17 \angle 26,9^\circ} = 744,1 \angle -26,9^\circ$$

$$V_B = 0,16 \times 744,1 = 119,1 \text{ V}$$

$$\bar{V}_B = 119,1 \angle -3,8^\circ$$

$$U_B = 206 \text{ V}$$

3)

$$I = 0 = \frac{\bar{V} - \bar{V}_B}{jX_T} \Rightarrow \bar{V} = \bar{V}_B \Rightarrow \text{HS aporta toda la activa y reactiva que consume la carga}$$

$$\bar{S}_2 = \sqrt{3} 219 \times \bar{I}_2^*$$

$$\bar{I}_2 = \frac{219}{0,16 \sqrt{3}} \angle -23,1^\circ = 791,2 \text{ A} \angle -23,1^\circ$$

$$P_2 = \sqrt{3} 219 \times 791,2 \angle 23,1^\circ = 299,8 \times 10^3 (0,92 + j 0,39) = 275,8 \text{ kW} + j 117 \text{ kVAR}$$


$$P_{HS} = 275,8 \text{ kW}$$

$$Q_{HS} = 117 \text{ kVAR}$$

4)

$$\frac{E}{\sqrt{3}} = jX_s \bar{I} + V_B$$

$$X_s = 91 \times \frac{230^2}{500 \times 10^3} = 0,011 \Omega$$



$$E = \sqrt{3} \times \sqrt{(26,6 + 3,4)^2 + 64} = \sqrt{3} \times 130 =$$

$$E = 225,3 \text{ V}$$

$$I = 2,25 \text{ A}$$

Problem 2

14/12/2018

1) $20 \times 745 = \frac{400^2}{R_{2e}} q(1-q) \stackrel{HPD.}{=} \frac{400^2}{0,36} q \Rightarrow q = 0,034 \rightarrow n_n = 1449 \text{ rpm}$

$$I_{2N} = \frac{400/\sqrt{3}}{0,36} \cdot 0,034 = 21,8 \text{ A} \rightarrow \bar{I}_{2N} = 21,8 \text{ A} \angle 0$$

$$\bar{I}_0 = 10 \angle -90 \Rightarrow \bar{I}_N = \sqrt{21,8^2 + 10^2} \angle -\arctan\left(\frac{10}{21,8}\right) = 24 \angle -24,6^\circ$$

2) $\cos \phi_0 = \cos 24,6 = 0,91$

$$P_{\text{min}} = \sqrt{3} \times 400 \times 24 \times 0,91 = 15,1 \text{ kW}$$

$$\eta = \frac{14900}{15100} = 0,987$$

3) $f = 60 \text{ Hz} \Rightarrow n_s = 1800 \text{ rpm}$ $P = 3,9 \times 10^{-5} \times 0,0625 \text{ m}^3 = 2,44 \times 10^{-6} \text{ m}^3$

$$P_m = \frac{400^2}{0,36} q(1-q) = 2,44 \times 10^{-6} \times 1800^3 (1-q)^3 \Rightarrow q = 0,032(1-q)^2 \Rightarrow \boxed{q = 0,03}$$

$$n = 1800 \times 0,97 = 1746 \text{ rpm} \quad Q = 109 \text{ l/min} \quad P = 13 \text{ kW}$$

$$I_{20} = \frac{400/\sqrt{3}}{0,36} \times 0,03 = 19,3 \text{ A}$$

$$I_0 = \frac{400/\sqrt{3}}{\frac{6}{5} \times 0} \angle -90 = \frac{5 \cdot 10}{6} \angle -90 = 8,33 \angle -90$$

$$I = \sqrt{19,3^2 + 8,33^2} = 21 \text{ A}$$

4) $Q = 100 \text{ l/min} \Rightarrow n = 1600 \text{ rpm} \Rightarrow P = 7984 \text{ W} = \frac{400^2}{R_{2e}} q(1-q)$

$$\Rightarrow q = 0,023 \Rightarrow 1600 = n_s(1-0,023) \Rightarrow n_s = 1638 \text{ rpm} = \frac{f \times 60}{2}$$

$$\boxed{f = 54,6 \text{ Hz}}$$