


Fracture in deck: Viewed from below deck, outboard,
and fwd. of hatch end beam



After failure: Close-up of tie-plate