


After failure: View from below deck, inboard,  
and fwd. of hatch end beam



After failure: Corner viewed from inside of hatch