


Corner viewed from inside of hatch



Deck and doubler fracture patterns - looking aft

FIG. 22 - SPECIMEN 18