


Overall view - below deck



Crack in doubler-deck weld

FIG. 8 - SPECIMEN 14