


Fracture in corner - viewed from inside of hatch



Deck and doubler fracture patterns, looking aft.