


Fractures viewed from above deck



Fractures viewed from below deck, outboard and forward of hatch end beam.