


Before failure: View of corner from above deck



Before failure: Below deck, looking aft and inboard

FIG. 12 - SPECIMEN 16