



Overall view - below deck




Overall view - above deck


FIG. 18 - SPECIMEN 17



Fractures: Viewed from above deck



Fractures: Viewed from below deck, outboard,
and aft of hatch end beam



Fractures: Viewed from below deck, outboard,
and fwd. of hatch end beam