


Fractures: Viewed from above deck



Fractures: Viewed from below deck, outboard, and fwd. of hatch end beam

FIG. 21 - SPECIMEN 18